



PUBLIC PARKS IMPROVEMENTS

SELLA BAY OVERLOOK TRAIL

1. PROBLEM

- Sub-standard trail conditions and some accessibility issues are not conducive to a scenic destination. Littering, parking issues and a general lack of security and amenities create a mixed atmosphere which can be distracting and dangerous.

2. SOLUTION

- The construction of Trailhead signage to help identify scenic trail start.
- The installation of a trail “walkway” with informational and directional signage to define a safe path free of erosion and loose soil.
- Scenic “Photo-op” rest stops to highlight 360° vistas of Guam including the southern mountain range and scenic views of Malesso, Humatak Bay, Sella and Cetti Bays and Cocos Island.
- Create and encourage Eco-tourism.
- Create a safe environment by providing security for parking and throughout the trail.



PUBLIC PARKS IMPROVEMENTS

SELLA BAY OVERLOOK TRAIL



Photo courtesy of Google Images

FIGURE 1
Existing Trailhead



Image courtesy of WB Flores & Assoc.

FIGURE 2
Conceptual Signage for Trailhead



PUBLIC PARKS IMPROVEMENTS

SELLA BAY OVERLOOK TRAIL



Photo courtesy of Google Images

FIGURE 3
Existing Trail Segments



Photo courtesy of Google Images

FIGURE 4
Existing Trail Segments



Photo courtesy of Google Images

FIGURE 5
Existing Trail Segments



PUBLIC PARKS IMPROVEMENTS

SELLA BAY OVERLOOK TRAIL




Photo courtesy of Google Images

FIGURE 6

Highlighted View of Existing Primary Trail



Photo courtesy of Google Earth

FIGURE 7

Bird's Eye View of Badlands and
Smaller Trails



PUBLIC PARKS IMPROVEMENTS

SELLA BAY OVERLOOK TRAIL



Image courtesy of WB Flores & Assoc.

FIGURE 8
Sella Bay Trail Improvements Site Limits